

# WR-Z16 MODEL

## Software Version 5.0: Release Notes

Safran (formerly Seven Solutions) released a software update for the WR-Z16 series. Customers can download this software update at no charge from the Safran Trusted 4D website (see [Downloading the Software Update](#)). This software update will upgrade the unit's system software to **Version 5.0**.

This update provides added benefits through new features, enhancements to existing functionality, as well as software fixes and security updates, as described in this document.

**Warning:** Ensure that you are using the correct file for your system to avoid complications.

# Table of Contents

Table of Contents .....	2
Version 5.0 .....	3
How to download and install the new SW .....	5
Downloading the Software Update .....	6
Installing the Software Update .....	6
How to contact Safran Technical Support .....	7

# Version 5.0

**Note:** The Web GUI has been newly designed from scratch, including a new REST API that has been deployed as a connection to the backend. With this we intend to provide a better user experience when using and connecting with our devices, in addition to improving performance and meeting branding change requirements.

**Note:** Integration of the PTP4L as PTP stack used in WR-ZYNQ-OS, in order to align with other devices inside of our company and improve our system having a stack that is under constant development. Currently we have integrated this stack with our parameter system and the wrapper we currently have, trying to keep the impact of the change to a minimum.

Please be aware that your previous PTP configuration file may not work properly with the new firmware.

**Note:** The leap seconds system has been intensively improved, allowing hot modification, deactivation of the expiration alert and fixing issues related to the application and transmission of leap seconds.

**Note:** Collectd has been disabled, because it was a deprecated and unmaintained system, which also consumed a lot of system resources and sometimes caused spam in the system log.

**Warning:** Due to the PTP4L PTP stack migration, Synchronous Ethernet (Sync-E) is not supported in this release. We expect to support in again in further releases.

## Newly released features

- api-rest: added a new API REST as user interface.
- www: improved the webui with a new design and using API REST for communication with the backend.
- ptp4l: migration from PTPd to PTP4L as PTP stack.
- ptp4l: added a new 61850-9-3 Power profile.
- ptp4l: removed support for the Telecom 8275.1 profile.
- ntp: added NTP Master functionality through fiber ports.
- tmgr: added a new parameter to disable the warnings generated when the leap seconds file expires.

## Enhancements and fixes

*The following improvements were applied and defects corrected on existing features and functions:*

#### *www:*

- disabled gpa\_json tool.

#### *wptp:*

- unit now only allow configuration of PTP mode if no license is available.
- updated license parameter description.

#### *ppsi:*

- fixed the transmission of leap second flags through the WR packets.
- fixed PPSi dying issue with several link reconnections.
- fixed an issue that caused PPSi to get stuck jumping between UNCALIBRATED state and SLAVE state under certain circumstances.

#### *ptp4l:*

- fixed the transmission of leap second flags through the PTP packets.

#### *ntp:*

- migrated from NTPd to chrony as NTP provider.
- fixed stratum configuration, can now be configured manually via UI.

#### *tmgr:*

- the leap seconds file can now be applied without restarting the device.
- updated leap-second file (valid until Jun-2024).
- removed unused timing source for GNSS.
- disabled auto mode in NTP stratum mode parameter.
- disabled copper ports to use PTP.
- disabled unsupported PTP slave mode.
- applied leap seconds functionality following the mechanism defined in the standard when leap59 or leap61 flags are detected in PTP packets coming from the master.
- fixed a cosmetic bug that showed the status of an interface as Slave when it was disabled.

#### *collectd*

- removed collectd service in the OS.

#### *sys:*

- rebranded the system prompt and LCD display (ZEN devices) information from Seven Solutions to Safran.

#### *security:*

- improved CA certificate generation with serial number randomization and change the Organization to Safran.
- reorganized HTTPs, expiration timeout and read only mode parameters to be shared between WEBUI via API REST.
- the http to https redirect is now non-cacheable.

#### *healthingd:*

- improved calculation of cpu usage and update cpu thresholds.

#### *snmp*

- fixed configuration problem that prevented to modify SNMPv3 password.
- fixed snmp traps objects description.

*hald:*

- fixed power supply temperature cosmetic problem, which shown a temperature when it was disconnected.

*libgpa:*

- fixed compatibility problems with ENUM parameters with string entries that were of numeric type.

*Known Issues*

- In the new Web UI, the “Value Applied” text after applying changes is not properly updated until the page is refreshed (from 5.0).
- In the holdover overview section of the new Web UI, the Time Learning label is actually counting the Time in Holdover, and vice versa (from 5.0).
- In some sections of the new Web UI, the hide button does not hide the Apply and Save buttons (from 5.0).
- The root password cannot be changed using an external authentication server (seen on previous versions).
- The Log Dump request via the new Web UI will generate the file under /opt/api-rest/\*.logdump, which occupies RAM (from 5.0)
- The Config File request will generate the file under /var/www/downloads/wrz\_config\_z\*, which occupies some RAM (from 5.0).
- In the NTP section of the new Web UI, the hide button in the NTP sources will instead hide the General configuration (from 5.0).
- Uploading files with a space in the name causes an error in the Web UI (seen on previous versions).
- Gateway and broadcast do not work properly; in hold, they are 0.0.0.0.after save and reboot (seen on previous versions).
- The `gpa_ctrl lldp` command contains outdated parameters `net/wrx/peer/1/port/timing` that are disabled and not updated by the LLDP daemon (from 5.0).
- ClockQ information is not properly reported in FR Master or GM without at least one active link in PPSi (seen on previous versions).
- Making a request to a parameter that does not exist through the REST API returns a code 200 (SUCCESS) instead of an error code (404) (from 5.0).
- An invalid configuration file entry through REST API returns error code 400 instead of 422 (from 5.0).
- In the network interfaces REST API, when an empty request is sent, the expected error code is 422, but 500 is returned (from 5.0).
- A percentage of odd-sized ethernet frames do not reach their destination. This is a minor problem since most of our services do not use odd packets and those that do, use TCP as the communication protocol (seen on previous versions).

# How to download and install the new SW

## Downloading the Software Update

The latest SecureSync software update can be downloaded from the Safran Navigation & Timing website under: <https://safran-navigation-timing.com/portal/public-downloads/latest-white-rabbit-product-update-files/>.

## Installing the Software Update

Detailed instructions on how to install the new software update can be found in the **WR-Z16 User Manual**:

<https://safran-navigation-timing.com/document/wr-z16-user-manual/>

In both the new and old Web UI, you can navigate to **Management > Firmware Update**. Drag and drop or browse files to upload the update.

# How to contact Safran Technical Support

Should you have any questions or comments regarding any of the above-mentioned features or fixes, please contact Technical Support:

<https://safran-navigation-timing.com/support-hub/>

Information furnished by Safran is believed to be accurate and reliable. However, no responsibility is assumed by Safran for its use, nor for any infringements of patents or other rights of third parties that may result from its use. Safran reserves the right to make changes without further notice to any products herein. Safran makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Safran assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. No license is granted by implication or otherwise under any patent or patent rights of Safran. Trademarks and registered trademarks are the property of their respective owners. Safran products are not intended for any application in which the failure of the Safran product could create a situation where personal injury or death may occur. Should Buyer purchase or use Safran products for any such unintended or unauthorized application, Buyer shall indemnify and hold Safran and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable legal fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Safran was negligent regarding the design or manufacture of the part.

Safran Electronics&Defence

- End of document -